

Certificate

Admission to implementation
of Volkswagen test regulations



by

Volkswagen AG
Materials technology

for

Leitat (Acondicionamiento Tarrasense)
Calle de la Innovacio 2
08225 Terrassa
Spain

The laboratory service provider **Leitat (Acondicionamiento Tarrasense)** has successfully compared the test procedures listed in the Appendix at the above-mentioned locations or at the aforementioned sub-suppliers with Volkswagen.

This certificate entitles the laboratory service provider to offer the tests listed in the Appendix worldwide as a certified laboratory service provider of Volkswagen **from 15.01.2024 to 14.01.2026**, in accordance with the regulations in the declaration of conformity issued by him.

Wolfsburg, den 12.01.2024

List of test procedures that can be offered to Volkswagen suppliers

Blatt 1 von 1

Service provider: **Leitat (Acondicionamiento Tarrasense)**

Region: **Europa**

Location or subcontracting in the attached location legend



Zertifiziert von
Volkswagen

Label	Description of test procedures	Note	Location
1 TL 1011	Flammability of non-Metallic Materials		A
2 PV 2034	Non-Metallic Planar Materials; Floating Roller Peel Test		A
3 PV 3906	Non-Metallic Planar Materials; Testing the Abrasion Behavior		A
4 PV 3968	Leather; Soiling Behavior		A
5 PV 3987	Scrub Resistance (Micro-Scratch Resistance) of High-Gloss Surfaces in the Vehicle Interior		A
6 PV 3989	Plastics for Components in the Exterior Area; Ball Drop Test		A
7 PV 3991	Structured surfaces, skin abrasion testing		A

Location legend:

Service provider: **Leitat (Acondicionamiento Tarrasense)**

Region: **Europa**

Nr.	Company name	Street	Place	Country
A	Leitat (Acondicionamiento Tarrasense)	Calle de la Innovacio 2	08225 Terrassa	Spain

